

There is a culvert in the Highway 18 ditch, in the middle of the field. A new culvert and access off the state road will likely be necessary and will require an INDOT permit.

**For more information, contact John Moss
217-898-5082 or loranda@loranda.com**